


AC/DC sensitive Residual current monitoring module RCMB101



RCMB101



RCMB101

Device features

- AC/DC sensitive residual current monitoring module
- r.m.s. value measurement (AC+DC)
- Frequency range 0...500 Hz
- · CT connection monitoring
- Completely shielded residual current transformer
- · Mechanical locking on the baseplate
- · RoHS-compliant

Approvals

ANSI/UL 1998



* File # E193871, UL 2231-2, "Standard for personnel protection systems for electric vehicle (EV) supply circuits: Particular requirements for protection devices for use in charging systems"

Product description

The AC/DC sensitive residual current monitoring module is suitable for fault current monitoring in charging stations where direct and/or alternating fault currents are likely to occur the value of which is constantly greater than zero. In combination with an external relay it is able to fulfill the requirement of UL 2231-2 for CCID20 protection devices for use in electric vehicle charging stations.

Function

Residual current monitoring is carried out using an internal measuring current transformer. The r.m.s. value is calculated by summing up the DC components included in the residual current and the AC components that are below the cut-off frequency. A signal in proportion to the residual current is available at the module analog output (X1). In addition, values outside the measuring range are signalled by a switching output (X12).

The control input (X10) will also be queried. Depending on the HIGH/LOW sequence, a reset of the RCMB101 will be activated with/without subsequent selftest with calibration and activation of the test winding.

Ordering information				
Туре	Measuring range	Frequency range	Art. No.	
RCMB101	0 20 mA	0500 Hz	B 9404 2098	




Technical data

Technical data		
Voltage supply		Specified time
$U_{\rm S}$ + (X11)	+ 12 V (± 1 V)	Operating time on X12 tae
$U_{S}-(X2)$	-12 V (± 1 V)	Operating time for choose
Ripple at U_S	≤ 100 mV	Recovery time t _b
Power consumption	≤ 1 W	Environmental condition
Measuring circuit		Without solar radiation, pr
Operating characteristic acc. to IEC 60755	UL2231 and IEC 60755 Type B	Classification of climatic co
Frequency range	0500 Hz	Stationary use (IEC 60721-
Measuring range	050 mA	Transport (IEC 60721-3-2)
Relative uncertainty	025 %	Long-time storage (IEC 60
Max. nominal current	50 A/4565 Hz	Classification of mechanica
Response value		Stationary use (IEC 60721-
Rated residual operating current I	20 mA	Transport (IEC 60721-3-2)
Detection circuit acc. to UL2231	CCID 20	Long-time storage (IEC 60
Detection circuit acc. to 0LZZ31	CCID 20	Deviation from the classifi
Inputs		Ambient temperature, du
Control input X10:		Ambient temperature, du
High level	4.55.5 V	Ambient temperature, dur Relative humidity
Low level	00.5 V	Air pressure
Outputs		•
Output voltage range	DC 0.15 V4.85 V	Connection
Sensitivity analogue output	1 V/10 mA	PCB plug connectors , sing
Tolerance at 1.510 mA	020 %/± 1 mA	Possible counter piece for
Tolerance at 1050 mA	020 %	
Tolerance at 0.15 V	+50/- 0 mV	Contact spacing
Tolerance at 4.85 V	-150/+ 50 mV	Other
Output resistance at the measurement output X1	1 k Ω (short-circuit proof)	Operating mode
Switching behaviour switching output X12 (Open Colle		Position of normal use
	values within the permissible measuring range	
High: values outsic	le the permissible measuring range	Software version Weight
Max. switching voltage X12	+ 24 V	y
Max. switching current X12	DC 10 mA	
Test winding		
Output voltage at X1 with a test current of 22.4 mA after		
Output voltage at X1 with a test current of 11 mA/400	Hz ≥ 1.1 V	


Operating time on X12 tae for $I_{\Delta n}$	< 990 ms
Operating time for choosen relay under nominal load	≤ 10 ms
Recovery time $t_{\rm b}$	≤ 2 5
Environmental conditions	
Without solar radiation, precipitation, water, icing. Condensa	ntion possible temporarily:
Classification of climatic conditions acc. to IEC 60721:	
Stationary use (IEC 60721-3-3)	3K5
Transport (IEC 60721-3-2)	2K3
Long-time storage (IEC 60721-3-1)	1K4
Classification of mechanical conditions acc. to IEC 60721:	
Stationary use (IEC 60721-3-3)	3M6
Transport (IEC 60721-3-2)	2M2
Long-time storage (IEC 60721-3-1)	1M3
Deviation from the classification of climatic conditions:	
Ambient temperature, during operation	-25+80 °C
Ambient temperature, during transport	-40+80 °C
Ambient temperature, during long-time storage	-25+80 °C
Relative humidity	1090 %
Air pressure	70106 kPa
Connection	
PCB plug connectors , single-row	0.65 x 0.65 mm
Possible counter piece for plug-in connector	Samtec: BCS-104-L-S-TE
	or 3M: 960104-6202-AR
Contact spacing	2.54 mm
Other	
Operating mode	continuous operation
Position of normal use	any
Software version	D359 V2
Weight	≤ 65 g

Application information

 Switching output X12 is used as hardware enable signal for the power contactor. Contactor is controlled by charger electronics software. Switching output X12 and analog output X1 are monitored by charger to verify that X1 and X12 show consistent information and that the behaviour after a test (initiated with X10) is correct.



2. Contactor controlled by charger electronics software. Switching output X12 and analog output X1 are monitored by charger to verify that X1 and X12 show consistent information and that the behaviour after a test (initiated with X10) is correct.



Important Note: Make sure to select a contactor and a driver circuit with a release time of less than 10 ms under nominal load condition of the charger.




Bender GmbH & Co. KG

P.O. Box 1161 • 35301 Grünberg • Germany Londorfer Straße 65 • 35305 Grünberg • Germany Tel.: +49 6401 807-0 • Fax: +49 6401 807-259 E-Mail: info@bender-de.com • www.bender-emobility.com


Dimension diagram

Dimensions in mm


Bender p.c.b. RCMB101 of 1.5 mm thickness



Bender p.c.b. on a base plate



Base plate of 1.7 mm thickness, tolerance: + 0.1/- 0 mm



X1 - M Analogue voltage output

X2 - U2 - U_5 Voltage supply -12 V via fuse 100 mA (recommended)

X3 - GND Ground

(4 - not connected

X9 - GND Ground

X10 - Control input 0...5 V

X11 - U1 + U_S voltage supply +12 V via fuse 100 mA

(recommended)

X12 - Switching output/alarm output (transistor, open collector)

9 - Working space to unlatch the p.c.b.